

Page1 of 1Certificate No:13/10Issue Date:21 JanExpiry Date:20 Jan

13/10023(E4)-04 21 January 2020 20 January 2025

<u>Appendix</u>

| RATINGS | Relay | Rating (A)/No. and type of contact |
|---------|-------------|------------------------------------|
| | RXM 2AB | 12 / 2 Open-Close |
| | RXM 3AB | 10 / 3 Open-Close |
| | RXM 4AB | 6 / 4 Open-Close |
| | RXM 4GB | 3 / 4 Open-Close |
| | Socket | Rating (V/A) |
| | RXZ E2S108M | 250 / 12 |
| | RXZ E2M114 | 250 / 10 |
| | RXZ E2M114M | 250 / 10 |
| | RXZ E2S114M | 250 / 10 |
| | RXZ E2S111M | 250 / 10 |
| | RXZ E2S114S | 250 / 12A for 2C/O, 6A for 4C/O |
| | RXZ E14P | 250 / 12A for 2C/O, 6A for 4C/O |

Tan Hui Luan Electrical Surveyor Electrotechnical Systems South Asia Technical Support Office, Singapore Lloyd's Register Singapore Pte Ltd Phone +65 3163 0701 Fax +65 6273 1662 Email: <u>hui-luan.tan@lr.org</u>

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.