

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L164862-42813-41101991-1
Report Reference E164862-19910114
Date 30-Nov-2021

Issued to: Schneider Electric Industries S A, DBA Telemecanique
8001 Knightdale Blvd Knightdale, NC
United States 27545

This is to certify that representative samples of NLDX7 - Motor Controllers, Magnetic Certified for Canada
See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: CSA C22.2 NO. 60947-4-1, 2nd Ed., Issue Date: 2014-04-04, Revised 2018-05, CSA C22.2 NO. 60947-1, 2nd Ed., Issue Date: 2013-07-31

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L164862-42813-41101991-1
Report Reference E164862-19910114
Date 30-Nov-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
LC1-D65 followed by two digits, may be followed by a suffix letter or number.	Magnetic Motor Controllers
Tesys offer , LC1-D65-004, followed by the coil voltage code denoted by a suffix letter and a digit, may be followed by a letter, may be followed by S335.	Magnetic Motor Controllers
Tesys offer , LC1-D65-008, followed by the coil voltage code denoted by a suffix letter and a digit, may be followed by a letter, may be followed by S335.	Magnetic Motor Controllers
Tesys offer , LC1-D65-6, followed by the coil voltage code denoted by a suffix letter and a digit, may be followed by a letter, may be followed by S335.	Magnetic Motor Controllers



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L164862-12813-41101991-1
Report Reference E164862-19910114
Date 30-Nov-2021

Issued to: Schneider Electric Industries S A, DBA Telemecanique
8001 Knightdale Blvd Knightdale, NC
United States 27545

**This is to certify that
representative samples of**

NLDX - Motor Controllers, Magnetic
See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 60947-1, 5th Ed., Issue Date: 2013-07-31, Revision
Date: 2019-05-06, UL 60947-4-1, 3rd Ed., Issue Date:
2014-04-04, Revision Date: 2017-10-17

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L164862-12813-41101991-1
Report Reference E164862-19910114
Date 30-Nov-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
LC1-D65 followed by two digits, may be followed by a suffix letter or number.	Magnetic Motor Controllers
Tesys offer , LC1-D65-004, followed by the coil voltage code denoted by a suffix letter and a digit, may be followed by a letter, may be followed by S335.	Magnetic Motor Controllers
Tesys offer , LC1-D65-008, followed by the coil voltage code denoted by a suffix letter and a digit, may be followed by a letter, may be followed by S335.	Magnetic Motor Controllers
Tesys offer , LC1-D65-6, followed by the coil voltage code denoted by a suffix letter and a digit, may be followed by a letter, may be followed by S335.	Magnetic Motor Controllers



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

