C02 - Supplier's declaration of conformity



For compliance levels 1, 2 and 3 in Australia

As required by the following Notices:

- Radiocommunications Devices (Compliance Labelling) Notice 2003 made under section 182 of the Radiocommunications Act 1992;
- Radiocommunications Labelling (Electromagnetic Compatibility) Notice 2008 made under section 182 of the Radiocommunications Act 1992:
- Radiocommunications (Compliance Labelling Electromagnetic Radiation) Notice 2003 made under section 182 of the Radiocommunications Act 1992; and
- Telecommunications Labelling (Customer Equipment and Customer Cabling) Notice 2001 made under section 407 of the Telecommunications Act 1997

Instructions for completion

 Do not return this form to the ACMA. This completed form must be retained by the supplier as part of the documentation required for the compliance records and must be made available for inspection by the ACMA when requested.

| kt PTY LTD (AUSTRALIA) It Address elen Street, Heidelberg West, VIC tralia POSTCODE 3081 | (issued by the ACMA prior to 1 March 2013) OR ABN ABN 81-006-054-468 |
|---|---|
| elen Street, Heidelberg West, VIC tralia POSTCODE 3081 | ABN |
| elen Street, Heidelberg West, VIC tralia POSTCODE 3081 | ABN |
| elen Street, Heidelberg West, VIC tralia POSTCODE 3081 | |
| elen Street, Heidelberg West, VIC tralia POSTCODE 3081 | ABN 81-006-054-468 |
| POSTCODE 3081 | |
| POSTCODE 3081 | |
| | · · · · · · · · · · · · · · · · · · · |
| luct family | |
| luct family | |
| luct family | · · · · · · · · · · · · · · · · · · · |
| | |
| | |
| FX3-CPU,MPL. | |
| | |
| wliana | |
| pliance | |
| | relevant ACMA Standards made under the Radiocommunications Act enced in notices made under section 182 of the Radiocommunication |
| ence of compliance is demonstrated by test reports to the following | applicable standards (see: page 2). |
| | |
| aration | |
| | t mentioned above complies with the relevant above mentioned standards and |
| by declare that the contents of this form are the and contect, that the product ots supplied under this declaration will be identical to the product identified al | · |
| Under section 137.1 of the <i>Criminal Code Act 1995</i> , it is an offence to know | • |
| ty: 12 months imprisonment | mgly provide laise of misleading information to a commonwealth entity. |
| ,, | |
| | |
| | MANAGING DIRECTOR |
| ATURE OF SUPPLIER OR AGENT | MANNING DIRECTOR POSITION IN ORGANISATION BATE 30/04/2014 |
| NAME DAVID DUNCHN | DATE 30/04/2014 |

Applicable standards

(count: 2)

Standard title, number and, if applicable, number of the test report

| Pos | Short.desc. | | | Dod | cument-No. | Issued | SICK-Id-No. | Pos-Exchg. |
|------|---------------|--------------|--------------|-----|--------------|------------|-------------|------------|
| 2010 | EMC, EMISSION | N INDUSTRIAL | ENVIRONMENTS | EN | 61000-6-4 | 2007-01-01 | 8605870 | |
| 2011 | EMC, EMISSIO | N INDUSTRIAL | ENVIRONMENTS | EN | 61000-6-4/A1 | 2011-02-01 | 8606052 | |

as of 2022-10-09

Product details (1-39 of 56)

Product description - brand name, type, model, lot, batch or serial number (if available)

| | Device-type |
|---------|-------------------|
| 1043700 | FX3-MPL000001 |
| 1043783 | FX3-CPU000000 |
| 1043784 | FX3-CPU130002 |
| 1045180 | FX3-MPL000001S01 |
| 1045258 | FX3-CPU000200 |
| 1045259 | FX3-CPU130202 |
| 1045262 | FX3-MPL000201 |
| 1047162 | FX3-MPL100001 |
| 1050609 | FX3-CPU000210 |
| 1050610 | FX3-CPU130212 |
| 1050613 | FX3-MPL000211 |
| 1050615 | FX3-CPU000010 |
| 1050616 | FX3-CPU130012 |
| 1050619 | FX3-MPL000011 |
| 1051170 | FX3-CPU000300 |
| 1051171 | FX3-CPU130302 |
| 1051180 | FX3-MPL000301 |
| 1058330 | FX3-MPL000001S02 |
| 1058863 | FX3-MPL000001S03 |
| 1058999 | FX3-CPU230002 |
| 1059305 | FX3-CPU320002 |
| 1062102 | FX3-MPL000001S04 |
| 1062103 | FX3-MPL000001S05 |
| 1064208 | FX3-MPL000001S06 |
| 1064209 | FX3-MPL000001S07 |
| 1064729 | FX3-MPL000001S08 |
| 1065157 | FX3-MPL000001S09 |
| 1067454 | FX3-CPU320202 |
| 1067455 | FX3-MPL100201 |
| 1067456 | FX3-CPU320212 |
| 1067457 | FX3-MPL100211 |
| 1067638 | FX3-CPU320302 |
| 1067639 | FX3-MPL100301 |
| 1070545 | FX3-CPU000400 |
| 1073314 | FX3-MPL000001S10 |
| 1073315 | FX3-MPL000001S11 |
| 1086537 | FX3-MPL000001S10 |
| | EV2 MDI 100001512 |
| 1090169 | FX3-MPL100001S12 |

as of 2022-10-09

Product details (40-56 of 56)

Product description - brand name, type, model, lot, batch or serial number (if available)

| SICK-ID-No. | Device-type |
|-------------|------------------|
| 1093859 | FX3-MPL000001S15 |
| 1095105 | FX3-MPL100001S17 |
| 1097070 | FX3-MPL000001S19 |
| 1097120 | FX3-CPU000220 |
| 1098440 | FX3-MPL100001S20 |
| 1102419 | FX3-CPU000040 |
| 1104930 | FX3-MPL000001S21 |
| 1106465 | FX3-CPU000050 |
| 1109314 | FX3-MPL000701 |
| 1109315 | FX3-CPU000700 |
| 1109316 | FX3-CPU130702 |
| 1111598 | FX3-MPL100001S23 |
| 1111599 | FX3-MPL100001S24 |
| 1112302 | FX3-CPU320012 |
| 1112303 | FX3-MPL100011 |
| 1124531 | FX3-MPL100001S26 |
| 1124533 | FX3-MPL100001S27 |

as of 2022-10-09