


CLASS J AMP-TRAP 2000 FUSE
CAT. NO. AJT (AMP)
70-100 AMPS 600 VOLTS AC

AVERAGE MELTING TIME-CURRENT CURVE

FERRAZ SHAWMUT
NEWBURYPORT, MA 01950

720043

CURRENT IN AMPERES



CURRENT IN AMPERES

CONTROL NO. 231
REV. -
10/24/01