UL Product **iQ**™

SWIV8.E172326 - Relay Sockets and Assemblies Certified for Canada - Component

Relay Sockets and Assemblies Certified for Canada - Component

See General Information for Relay Sockets and Assemblies Certified for Canada - Component

SCHNEIDER ELECTRIC INDUSTRIES S A, DBA TELEMECANIQUE

E172326

8001 Knightdale Blvd

Knightdale, NC 27545 USA

Relay sockets, Model(s) RPZF1, RPZF2, RPZF3, RPZF4, RUZC2M, RUZC3M, RUZSC2M, RUZSF3M, RUZXC3M, RXZE2M114, RXZE2S114M, RXZE2S111M, RXZE2S114M

Relay sockets and assemblies, Model(s) RGZ E1S35M, RGZ E1S48M, RSLZRA1, RSLZRA2, RSLZRA3, RSLZRA4, RSLZVA1, RSLZVA2, RSLZVA4, RXZE14P, RXZE2S114S, SSLZRA1, SSLZRA2, SSLZRA3, SSLZRA4, SSLZVA1, SSLZVA2, SSLZVA3, SSLZVA4

Marking: Company name or trademark Schneider , model designation and the Recognized Component Mark for



Last Updated on 2019-07-10

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL's Follow-Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL's Follow-Up Service. Always look for the Mark on the product.

UL permits the reproduction of the material contained in the Online Certification Directory subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from the Online Certifications Directory with permission from UL" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "© 2020 UL LLC"