



# Certificate of Compliance

**Certificate:** 1155282 (043364\_S\_000)

**Master Contract:** 164581

**Project:** 70048344

**Date Issued:** 2016-05-27

**Issued to:** Telemecanique/Schneider Electric Industries SAS  
31 rue Pierre Mendes France  
Eybens, 38320  
FRANCE

*The products listed below are eligible to bear the CSA Mark shown*



*Patrick Quinty, Eng*

**Issued by:**  
**Patrick Quinty, Eng.**

## **PRODUCTS**

CLASS - C321103 - INDUSTRIAL CONTROL EQUIPMENT-Motor Controllers - Auxiliary Devices

Input and indicator modules, interface module LA4-DF, -DL, automatic/manual stop module -DM, solid state interface module -DW, indicator module -DV and coil suppressor modules, LA4-DA, RC circuit, -DC "diode" and -DE varistance. Electronic timer module, LA4-DT., LA4-DR., 24...240V ac/dc.

## **APPLICABLE REQUIREMENTS**

CSA-C22.2 No. 14-13 - Industrial Control Equipment

## **MARKINGS**

- Submitter's name, catalogue number, electrical rating and the CSA Mark appear on each product.
- Installation instructions are provided with the device.



## *Supplement to Certificate of Compliance*

**Certificate:** 1155282 (043364\_S\_000)

**Master Contract:** 164581

*The products listed, including the latest revision described below, are eligible to be marked in accordance with the referenced Certificate.*

### **Product Certification History**

<b>Project</b>	<b>Date</b>	<b>Description</b>
70048344	2016-05-27	FIR Non-compliance at FC235794 on Aug 27 2015. Update Report 1155282 for component interchangeability - Components: - Use alternate triac model # BTB 12600C or 12600CRG manufacturer by ST-electronic (Recognized by UL file # E81734), alternate Diode Bridge model # W08G manufacturer by Vishay (Recognized by UL file # E54214) and alternate relays: model RY613024 for module LA4-DFB, models JS-24MN-KT and RYA32005 for module LA4-DLE.
1155282	2000-12-13	Use of alternate thyristor S820-600T on LA4-DR24. <b>Report 164581-1155282 supersedes report LR 43364-61.</b>
LR 43364-140	1998-02-24	Alternate plastic material for housing and report update.
LR 43364-61	1992-01-13	- Input indicator modules and coil suppressors Types LA4. <b>Report LR 43364-61 is superseded by number 164581-1155282.</b>